

# Inspection Photos

API: 061-06488

Operator: CHEMCO INC

Inspection Date: 8/9/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06488 - Date: 8/9/2023

## Inspection Photos



**Photo 1.** Facing east near the tank battery. There is erosion along the access road in this area that needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06488 - Date: 8/9/2023

## Inspection Photos



**Photo 2.** Facing northeast toward the tank battery. There is oil stained soil at red arrow that needs to be cleaned up. Berm does not appear to be adequate for containment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06488 - Date: 8/9/2023



## Inspection Photos



**Photo 3.** Facing north along the access road. The cattle guard is filled in with sediment and needs maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06488 - Date: 8/9/2023

## Inspection Photos



**Photo 4.** Facing toward the pumpjack. The chemical container has fallen over and does not have secondary containment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06488 - Date: 8/9/2023



## Inspection Photos



**Photo 5.** There is oil stained soils shown at red arrow that need to be cleaned up..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06488 - Date: 8/9/2023

## Inspection Photos



**Photo 6.** The fence around the tank battery is not maintained..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06488 - Date: 8/9/2023