

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2023

Submitted Date:

08/14/2023

Document Number:

708901348

FIELD INSPECTION FORM

Loc ID: 335291 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

Findings:
 23 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211487	WELL	PR	04/25/1998	GW	045-07247	SAVAGE RMV 98-28	PR
211488	WELL	PR	04/25/1998	GW	045-07248	SAVAGE RMV 101-28	PR
262450	WELL	PR	04/18/2002	GW	045-08029	SAVAGE RWF 312-28	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 08/14/2023 at approximately 12:59 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RU28 Pad/Production facility. Location # 335291 in Garfield County Colorado.
 Please refer to inspection 702801392 conducted on 03/23/2023, previous corrective actions have been completed.
 Location is within High Priority/Density/Black Bear Habitat areas & Bald Eagle Roost Site & in close proximity to NSO habitat area.
 Location is approximately 296 yards from the Colorado River.
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- Housekeeping - Stained soils and gravel on location with a CA date of 08/24/2023.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Split pad/Remote location - Shared facilities with the SAVAGE RMV-35-28 pad location # 323914 & the RMV 129-29 pad location # 335243

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Small amount of weeds in tank battery secondary containment		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Type	OTHER		
Comment:	Stained soils and gravel on location behind RMV 98-28 & RMV 101-28 production unit.		
Corrective Action:	Remove and properly dispose of all stained soils and gravel		Date: 08/24/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	No form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Cata-Dyne		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLs	STEEL AST		,	
Comment: Separate containment						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 500 gal						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient			
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment: Centralized containment						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient			
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment: Centralized containment						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		

Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: <u>211487</u>	Type: <u>WELL</u>	API Number: <u>045-07247</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>211488</u>	Type: <u>WELL</u>	API Number: <u>045-07248</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>262450</u>	Type: <u>WELL</u>	API Number: <u>045-08029</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small areas of light compaction
Gravel						Sparse in some areas
		Compaction				
		Gravel				Sparse in some sections

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping for observed compliance issue.	smelserw	08/14/2023
Split pad/Remote locations - Shared facilities with the SAVAGE RMV-35-28 pad location # 323914 & the RMV 129-29 pad location # 335243		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901351	Inspection 708901348 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6218424
708901352	Inspection 708901348 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6218425