

Location

Overall Good:

Signs/Marker:

	Type OTHER		
Comment:	Rig access sign is adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 264390 Type: WELL API Number: 123-21062 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: Axis Energy

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Rig crew running a inflatable packer in the well to locate and seal any migrating gas so they can complete the P & A on the well.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 8-14-2023 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Inspection due to Form 42 notices, MIRU Doc # 403485175 & PA Doc #403485183. Operator: Civitas/Crestone Peak Resources Location name: Federal NOAA 11-32 API #05-123-21062 County: Weld Weather: Clear, Sunny. Location: Dry. While there, I observed a wellsite, active plugging operations at the time of the inspection. During this inspection, I observed no compliance issues: See attached photos. I spoke with Civitas Company Man Hector Terazas about the current operations (running an inflatable packer down hole). No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	08/14/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402193	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6218414