

Final Reclamation Inspection

July 15, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 319113

Inspection Document #: 701900991

NWSE Section 28 T6N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Davis Farms 33-28
Location ID: 319113




Photo 1. 2023 aerial imagery of the well pad, access road and associated tank battery (north is up).

Inspection Photos
Location Name: Davis Farms 33-28
Location ID: 319113



Photo 2. Overview photo of the well pad taken from the western edge facing east.

Inspection Photos
Location Name: Davis Farms 33-28
Location ID: 319113



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Davis Farms 33-28
Location ID: 319113



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with adjacent reference area (see photo #5).

Inspection Photos
Location Name: Davis Farms 33-28
Location ID: 319113



Photo 5. Overview photo of the tank battery taken at ground level from the southern edge facing north. Photo shows that the western edge of the tank battery shows stunted crop growth and bare ground which does not appear consistent with adjacent crop reference area.



Inspection Photos
Location Name: Davis Farms 33-28
Location ID: 319113



Photo 6. Reference Area.