

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/10/2023

Submitted Date:

08/15/2023

Document Number:

705000395

**FIELD INSPECTION FORM**

Loc ID 328480 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248243	WELL	SI	01/01/2019	GW	123-16041	HSR-COOPER 12-10A	PA
328480	LOCATION	AC			-	HSR-COOPER-63N66W 10NWSW	EG

**General Comment:**

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)  
[Photos uploaded](#)

**Inspected Facilities**

Facility ID: 248243 Type: WELL API Number: 123-16041 Status: SI Insp. Status: PA

**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: ECMC Inspector met with Oxy contract personnel on location. Well (HSR-Cooper 12-10A) has been plugged and abandoned. ECMC form 42 notice of start of plugging operations doc #403425458 received 06/07/2023. OLF WH flowline removal work is pending; per communications, OLF WH flowlines have been AIP and are scheduled for full removal once crop field is harvested. Flowline cut ends (2) observed at WH excavation (in addition (2) historically abandoned flowline cut ends were observed at WH/ scheduled for removal). Fenced excavations observed at facility/ battery area; (2) WH flowline risers (isolated/ bullplugged) were observed at facility excavation. Facility/ battery decommissioning is completed (tanks/ equipment removed). On location dump and process flowline removal work at facility/ battery is completed. Excavation/ remediation work (per form 27) is in progress.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 328480 Type: LOCATION API Number: - Status: AC Insp. Status: EG

**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403487855 received on 08/09/2023: On August 7, 2023, historically impacted soils were discovered following facility decommissioning operations at the Cooper 12-10A O SA facility location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	08/15/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000401	Excavation at PA well; FL cut end capped	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6219192">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6219192</a>
705000402	Flowlines exposed in WH excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6219193">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6219193</a>
705000403	Excavations at facility; location signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6219194">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6219194</a>