

Inspection Photos
Location Name: Thomas East #1
Location ID: 443574



Energy & Carbon Management Commission
40.84073, -104.88711, 1693.2m, 227°
08/15/2023 12:12:03

Lease road entrance



Energy & Carbon Management Commission
40.84067, -104.89088, 1695.5m, 266°
08/15/2023 12:14:24

Production facility

Inspection Photos
Location Name: Thomas East #1
Location ID: 443574



Energy & Carbon Management Commission
40.84079, -104.89163, 1688.6m, 356°
08/15/2023 12:16:26

Disconnected ECD with pilot on



Energy & Carbon Management Commission
40.84076, -104.89151, 1691.6m, 10°
08/15/2023 12:16:33

Pilot gas valve

Inspection Photos
Location Name: Thomas East #1
Location ID: 443574



Tank connected inlet shut in ECD



Pilot display

Inspection Photos
Location Name: Thomas East #1
Location ID: 443574



Tank connected inlet open ECD



Pilot display

Inspection Photos
Location Name: Thomas East #1
Location ID: 443574



Tank connected ECD inlet valve position



Unused equipment

Inspection Photos
Location Name: Thomas East #1
Location ID: 443574



Unused equipment



Unused equipment

Inspection Photos
Location Name: Thomas East #1
Location ID: 443574



Unused equipment



Stained soil

Inspection Photos
Location Name: Thomas East #1
Location ID: 443574



Chemical system placards



Chemical system placards

Inspection Photos
Location Name: Thomas East #1
Location ID: 443574



Condensate placards



ECD positions