

**Inspection Photos**  
**Location Name: Champlin 246 Amoco A #1**  
**API # 05-123-10084**



**Appears to be the flow line**

