

Inspection Photos
Location Name: CAERUS PICEANCE LLC H26NW Pad
Location #: 335314



Photo # 5801 From entrance to location



Photo # 5802 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H26NW Pad
Location #: 335314



Photo # 5803 From entrance to location



Photo # 5804 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC H26NW Pad

Location #: 335314



Aug 15, 2023 at 10:14:18 AM
CO

Photo # 5808 Location



Aug 15, 2023 at 10:14:35 AM
CO

Photo # 5809 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H26NW Pad
Location #: 335314



Photo # 5810 Location



Photo # 5811 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H26NW Pad
Location #: 335314



Photo # 5812 Location



Photo # 5813 Stained gravel in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC H26NW Pad
Location #: 335314



Photo # 5818 Stained gravel in secondary containment



Photo # 5819 Flowline heating insulation open ended