

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2023

Submitted Date:

08/16/2023

Document Number:

700901631

**FIELD INSPECTION FORM**Loc ID 320391 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                         | Comment                         |
|--------------|-------|-------------------------------|---------------------------------|
| ,            |       | Inspections@civiresources.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 203629      | WELL | SI     | 08/01/2018  | GW         | 001-09189 | HSR LAWSON 8-3 | SI          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Type: Bradenhead                  | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Bird Protectors             | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Plunger Lift                | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Gas Meter Run               | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |  |
|--------------------|---|----------|-----------|---------|-----------------------|--|
| CRUDE OIL          | 1 | 300 BBLS | STEEL AST |         | 39.908421,-104.754502 |  |
| Comment:           |   |          |           |         |                       |  |
| Corrective Action: |   |          |           |         | Date:                 |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|------|----------|---------------------|---------------------|-------------|

|                    |          |                  |                 |          |       |
|--------------------|----------|------------------|-----------------|----------|-------|
| Earth              | Adequate | Walls Sufficient | Base Sufficient | Adequate |       |
| Comment:           |          |                  |                 |          |       |
| Corrective Action: |          |                  |                 |          | Date: |

**Wells Served By Facilities Above****AirsID**

API Number

API Number

AirsID

001-09189

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**Facility ID: 203629 Type: WELL API Number: 001-09189 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 04/12/2022 Annual Brhd Completed? \_\_\_\_\_Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: Appeared to be plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment                   | User     | Date       |
|---------------------------|----------|------------|
| <u>Routine inspection</u> | finkenbc | 08/16/2023 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 700901632    | INSPECTION PHOTOS | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6220414">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6220414</a> |