

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N36NW Pad
Location #: 334944



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 36 6S93W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N36NW Pad
Location #: 334944



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N36NW Pad
Location #: 334944



Photo # 5950 Tunnel erosion/sink hole (SW corner of location)

Photo # 5951 Tunnel erosion/sink hole (SW corner of location)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N36NW Pad
Location #: 334944



Photo # 5952 Tunnel erosion/sink hole (SW corner of location)



Photo # 5953 Tunnel erosion/sink hole/insufficient runoff controls/BMP's (NW corner of location in ditch)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N36NW Pad
Location #: 334944



Photo # 5954 Tunnel erosion/sink hole/insufficient runoff controls/BMP's (NW corner of location near ditch)



Photo # 5990 Ditch needs maintenance (west side of road just after you turn onto spur road, near aluminum shed & grain bins)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N36NW Pad
Location #: 334944



Photo # 5991 Ditch needs maintenance (west side of road just after you turn onto spur road, near aluminum shed & grain bins)



Photo # 5992 Ditch needs maintenance (west side of road just after you turn onto spur road, near aluminum shed & grain bins)