

**KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252**



Access road to location



Entrance to location

**KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252**



Additional information required when replaced



Weeds

KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252



Unmarked anchor




Weeds

**KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252**



Tank berm failure



Tank berm failure

**KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252**



Tank berm failure




Tank berm failure

KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252



Weeds



Calibration overdue

KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252



Weeds



Lack of Stormwater BMPs

**KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252**



Lack of Stormwater BMPs



Lack of Stormwater BMPs

**KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252**



Lack of Stormwater BMPs



Lack of Stormwater BMPs

**KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252**



Lack of Stormwater BMPs



Lack of Stormwater BMPs

**KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252**



Location from Southwest corner



Location from Northwest corner

**KT Resources LLC
WRD Wyatt 25-33
Loc ID: 316252**



Location from Northeast corner



Location from Southeast corner