

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/11/2023

Submitted Date:

08/16/2023

Document Number:

698600929

**FIELD INSPECTION FORM**Loc ID 336974 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chambers, Kit		Kchambers@ravenwoodlabs.com	
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
, Engineering		dnr_cogccengineering@state.co.us	
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281152	WELL	PR	03/04/2007	GW	125-09642	BLED SOE 3-26-5-45	PR

**General Comment:**

Follow up Inspection conducted due to initial findings during Routine Inspection completed 08/02/2023 document number 698600868. Follow-up Inspections were completed 08/07/2023 document number 698600895 and 08/10/2023 document number 698600921.

The Routine Inspection was conducted in response to Landowner reporting damage to irrigation system pivot arm coming into contact with tubing sticking out of the wellbore. Tubing was forced over by Pivot Arm and split approximately 6" above well cap. Split in tubing is allowing well to continuously vent gas.

Operator stated via email that the well was secure 08/10/2023 at 7:23 PM.

Inspector arrived at well location 08/11/2023 at approximately 1:15 PM and found the well in the same state it was in 08/02/2023 venting gas to atmosphere from the split in the tubing. Further investigation revealed that the adjacent well the Bledsoe 4-26-5-45 API number 125-09611 had been serviced and the damaged tubing there had been removed from the wellbore. I notified the Operator 08/11/2023 1:59 PM via email that the Bledsoe 3-26-5-45 API number 125-09642 had not been repaired and was still venting gas and that I believed the service company had mistakenly worked on the adjacent well (Both Wells were leaking 08/02/2023).

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	<p>Tubing with valve in wellbore appears to of been pushed by gas pressure high enough it came into contact with irrigation system pivot arm and is bent over. Tubing has split at bend and is venting uncontrolled.</p> <p>Follow up Inspection 8/7/2023 - Well is continuing to vent to atmosphere.  Follow up Inspection 8/10/2023 - Well is continuing to vent to atmosphere.  Follow up Inspection 8/11/2023 - Well is continuing to vent to atmosphere.</p>		
Corrective Action:	<p>Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).</p> <p>Follow up Inspection 8/11/2023 - Corrective Action Date remains the same to document noncompliance.</p>		Date: 08/03/2023

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	281152	Type:	WELL	API Number:	125-09642	Status:	PR	Insp. Status:	PR

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600941	Well Sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222410">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222410</a>
698600942	08/11/2023 Tubing Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222411">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222411</a>