

Inspection Photos

Location Name: Wayne/5N64W22 1-10

Location ID: 329128



Photo #1

Wayne/5N64W22 1-10 pad

Battery site

Active



Photo #2

Wayne/5N64W22 1-10 pad

Battery site

Active

Crude oil tank(s): SE corner



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wayne/5N64W22 1-10

Location ID: 329128



Photo #3

Wayne/5N64W22 1-10 pad

Battery site

Active

Produced H₂O tank(s): SE corner



Photo #4

Wayne/5N64W22 1-10 pad

Battery site

Active

Flow through surge tank



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Wayne/5N64W22 1-10

Location ID: 329128



Photo #5

Wayne/5N64W22 1-10 pad

Battery site

Active

ECD(s)



Photo #6

Wayne/5N64W22 1-10 pad

Battery site

Active

Separator(s)



Inspection Photos

Location Name: Wayne/5N64W22 1-10

Location ID: 329128



Photo #7

Wayne/5N64W22 1-10 pad

Battery site

Active

VRU, Compressor



Photo #8

Wayne/5N64W22 1-10 pad

Battery site

Active

LACT, IAU(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Wayne/5N64W22 1-10

Location ID: 329128




Photo #9

Wayne/5N64W22 1-10 pad

Battery site

Active

Facility / Battery sign



Photo #10

Wayne/5N64W22 1-10 pad

Wellsite(s): 10

Producing | PR

Well names / API: documented on FIR doc #707601687.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources