

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2023

Submitted Date:

08/01/2023

Document Number:

694100121**FIELD INSPECTION FORM**Loc ID 329818 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kilcrease, Keith		keith.kilcrease@anadarko.com	
,		COGCCInspections@Oxy.com	All Inspections
Avant, Paul	720-929-6457	Paul.Avant@Anadarko.com	

**General Comment:**

This is an environmental inspection for Location ID 329818 Markham Facility. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	<input type="text"/>	<input type="text"/>	<input type="text"/>
Comment:	<input type="text"/>	<input type="text"/>	<input type="text"/>
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

**Flaring:**

Type	<input type="text"/>	<input type="text"/>
Comment:	<input type="text"/>	<input type="text"/>
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Moderately sized leak/soil stain is visible at the meter house.Corrective Action: Stained soil identified at various locations through out location. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.. (2).DDate: 08/08/2023

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403483239	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6201428">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6201428</a>
694100122	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6201422">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6201422</a>