

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2023

Submitted Date:

08/11/2023

Document Number:

701103796

FIELD INSPECTION FORM

Loc ID 323864 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211035	WELL	SI	12/01/2022	GW	045-06793	GASAWAY (FEDERAL) 6206 (27-1)	EG

General Comment:

Flowline integrity inspection

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: Unused equipment/flowline risers at the separator and tank battery.

Corrective Action: Comply with Rule 606
Immediately within 24 hours comply with OOSLAT requirements per Rule 1101.a.(3).C.
(isolate and tag)

Date: 09/15/2023

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Flow Line # 3

Comment: 3 open ended 1' risers at the tank battery.

Corrective Action:

Date:

Type: Flow Line # 4

Comment: 1- 1" open ended riser at separator
2- 1" risers tied together marked do not operate at separator
1- 2" riser bull plugged with out OOSLAT tag/making

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 211035 Type: WELL API Number: 045-06793 Status: SI Insp. Status: EG

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: _____

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403494101	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215721
701103797	Flowline integrity inspection 701103796 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215719