

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2023

Submitted Date:

08/11/2023

Document Number:

712700505

**FIELD INSPECTION FORM**Loc ID 306993 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 7125

Name of Operator: BEEMAN OIL &amp; GAS INC

Address: 13635 E 104TH AVENUE STE 400

City: COMMERCE CITY State: CO Zip: 80022

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Galloway, Kelly		kgallowaywerc@gmail.com	All SW field inspections
, Engineering		dnr_cogccengineering@state.co.us	
Lindley, Trent		trent.lindley@state.co.us	
Stepp, Sarah		wccassistant@gmail.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292161	WELL	SI	06/01/2022	OW	067-09390	HUBBS 2	SI

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt two-track		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Present	Date:	
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Corrective action identified in FIR Doc#702500069 completed.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	IGNITOR/COMBUSTOR		
Comment:	T-post and hog wire.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electrical box, T-post and hog wire.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Pipe fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead not accessible. Corrective action identified in FIR Doc.#702500069 submitted 6/3/2022 not completed.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date:

Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical box		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Combustor		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	1-2" line from wellhead to combustor. 1-2" line to offsite remote tank battery.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:	Combustor hooked up to casing head, not combusting or venting at time of inspection, no current approved Sundry to vent/flare, no gas capture plan of Rule 903 variance in process.		
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 292161 Type: WELL API Number: 067-09390 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: Fluid Type: End Surf Csg Pressure: Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Location vegetated, tear drop around production equipment.  
No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403494346	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215944">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215944</a>
712700510	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215940">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215940</a>