

# Inspection Photos

API: 071-09004

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2023



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/16/2023

## Inspection Photos



**Photo 1.** Facing southeast along the access road near the location. There is erosion along this area of the road that needs to be repaired and stabilized.



## Inspection Photos



**Photo 2.** Facing north toward the access road at the location. There is erosion along the road side at the location.



## Inspection Photos



**Photo 3.** Facing southwest at the location. This portion of the location is not stabilized with vegetation cover and has signs of erosion.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 071-09004 | Date: 8/16/2023

## Inspection Photos



**Photo 4.** Facing east at the location. This portion of the location is not stabilized with vegetation cover and has signs of erosion.



## Inspection Photos



**Photo 5.** West side of the location facing northeast. There are noxious weeds at red arrow (Canada thistle). Some of the weeds were wilted from weed control but some were not controlled.



## Inspection Photos



**Photo 6.** Facing northwest at the location. Well marker is shown in this photo.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API: 071-09004 | Date: 8/16/2023

## Inspection Photos



**Photo 7.** East side of the location facing northwest at the bottom slope.



## Inspection Photos



**Photo 8.** There were more noxious weeds at the northeast side of the location. Some of the noxious weeds observed were wilted from recent weed control.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 9.** Southeast side of the location facing west. This portion of the location is not stabilized with vegetation cover and has signs of erosion.



## Inspection Photos



**Photo 10.** Facing southeast down the bottom of the location. This portion of the location is not stabilized with vegetation cover and has signs of erosion.



## Inspection Photos



**Photo 11.** Facing south at the location. The vegetation at the mid portion of the location appears to be well established.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 12.** Northeast side of the location facing southwest. There are areas of the location that will need to be reseeded.

