

Inspection Photos
Maralex Conley 7
API 007-06246



Photo #1. Weeds around containment berm.



Photo #2. Weeds around the wellhead/pumpjack..



Inspection Photos
Maralex Conley 7
API 007-06246




Photo #3. View of corrective action identified in Doc.#702500281.



Photo #4. View of no tank volume labeling. Corrective action not completed.

