

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2023

Submitted Date:

08/18/2023

Document Number:

712700537

FIELD INSPECTION FORMLoc ID 320908 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		Maralextech@gmail.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295374	WELL	PR	11/19/2008	CBM	007-06246	CONLEY 7	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #702500281 submitted on 7/26/2022.

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank volume capacity not displayed. See Photos #3 & #4. Corrective action identified in FIR Doc.#702500281. Corrective action date is retained.		
Corrective Action:	Install sign to comply with Rule 605.h	Date:	08/25/2022
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Present	Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds growing around wellhead/pumpjack, and produced water tank. See Photos #1 & #2.		
Corrective Action:	Remove weeds per rule 606.	Date:	09/01/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Wellhead and pumpjack, cattle panel.		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas motor.		
Corrective Action:		Date:	

Type: Flow Line	# 3	
Comment:	3" line from wellhead to separator. 1" line from separator to prime mover. 1" line from separator to produced water tank heater.	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	3" line from separator to meterhouse. Calibrated within one year.	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		37.000680,-107.442740
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 295374 Type: WELL API Number: 007-06246 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 08/17/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Ditches	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700544	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6225056