

Inspection Photos
Location Name: CAERUS PICEANCE LLC L1B Pad
Location ID: 334851



Photo # 6134 From entrance to location



Photo # 6135 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC L1B Pad
Location ID: 334851



Photo # 6138 Location



Photo # 6139 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC L1B Pad
Location ID: 334851



Photo # 6140 Location



Photo # 6142 Flowline heating insulation open ended

Inspection Photos
Location Name: CAERUS PICEANCE LLC L1B Pad
Location ID: 334851



Photo # 6151 Flowline heating insulation open ended



Photo # 6153 Debris