

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/18/2023

Submitted Date:

08/20/2023

Document Number:

707601701

FIELD INSPECTION FORM

Loc ID 322940 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244498	WELL	TA	07/01/2018	OW	123-12293	KOHLER 8-21	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID (322939).
(Well(s): 1: Temporarily Abandoned | TA).

Centralized Battery formerly served 2 Location IDs (322938, 322940).
(Well(s): 2: Plugged & Abandoned | PA).

Reference: Field Inspection Report doc. #707601699 and/or Location ID #322939 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead fencing / signage remains in place. LOTO Flowline header protected by fence.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel. Wellhead fencing / signage remains in place. LOTO Flowline header protected by fence.		
Corrective Action:		Date:	
Equipment:			
Type: Emission Control Device	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment assigned to Loc. ID #322939.		
Corrective Action:		Date:	
Type: Pig Station	# 0		
Comment:	Plugged & Abandoned PA. Equipment assigned to Loc. ID #322939.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Plugged & Abandoned PA. Equipment assigned to Loc. ID #322939.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Plugged & Abandoned PA. Equipment assigned to Loc. ID #322939.		
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0					
Comment: Plugged & Abandoned PA. Equipment assigned to Loc. ID #322939.						
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0					
Comment: Plugged & Abandoned PA. Equipment assigned to Loc. ID #322939.						
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 244498 Type: WELL API Number: 123-12293 Status: TA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 08/18/2023 at approximately 11:08 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: KOHLER-65N64W/21SENE Location ID: 322940 Well Name(s): Kohler 8-21. API: 123-12293. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (322939). (Well(s): 1: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 2 Location IDs (322938, 322940). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Reference: Field Inspection Report doc. #707601699 and/or Location ID #322939 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6I on file. PA Notice of Intent: 10/21/2021. Approved. Form 42 on file. PA Notice: 11/10/2021. Approved. Form 17 on file. Brhd test: 05/25/2023. 0-psi, No fluid or gas present. Approved. Form 6S NOT on file. Plugging, cut/cap: Completed. Cut/Cap date: unknown. Plugged & Abandoned PA well GPS coordinates: 40.386704 / -104.547877</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601702	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6225347