

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2023

Submitted Date:

08/21/2023

Document Number:

698600937

**FIELD INSPECTION FORM**

Loc ID 303113 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 38 PALMER CREST CT  
City: SPRING State: TX Zip: 77381

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 22 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252480	WELL	PR	07/04/1980	GW	125-06355	ECKLEY-KITZMILLER 1-5	PR

**General Comment:**

[Routine Inspection.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Well sign located at two track and main access road intersection.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign posted on Meter Shed door.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Contents/Quanity/Hazard Placard on Produced Water Open Top is unreadable.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	10/21/2023
Type	WELLHEAD		
Comment:	Well sign located on well fencing		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	No Emergency contact information posted at Produced Water Open Top Pit.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/21/2023
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soils around wellhead and pumping unit.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	09/21/2023
Type	UNUSED EQUIPMENT		
Comment:	Pump Jack belt drive guard noted on ground inside fencing.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock Panel Fencing around surface equipment at well location.		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Stock Panel Fencing around Open Top Pit location.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stock Panel Fencing around Gas Meter Run location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Pump Jack Cement Pad.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead Plumbed to surface.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Metal Meter Shed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in wellbore. Tubing valve open. Casing valve open.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	
Type: Gas Meter Run	#		
Comment:	Gas Meter Run. Chart in Meter Box dated 8-1-23. Meter Calibration/Test Log dated 3-27-23. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		40.255000,-102.419610
Comment:	Fiberglass Open Top pit with Wildlife screening (wire netting). Pit Contents/Quantity/Hazard Placard is unreadable. No emergency contact information posted.				
Corrective Action:					Date:

**Paint**

Condition	
-----------	--

Other (Content)	
Other (Capacity) 210 BBLS	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 252480 Type: WELL API Number: 125-06355 Status: PR Insp. Status: PR

**Producing Well**

Comment: Rods and tubing in wellbore. Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.

Electronic Well File reflects last Production/Status reported 6/1/2023 and Well Status as PR. Based on current valve settings the well is PR.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600962	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6226085">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6226085</a>