

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/22/2023

Submitted Date:

08/22/2023

Document Number:

702402252

FIELD INSPECTION FORM
 Loc ID 336456 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251777	WELL	PR	05/15/2023	OW	123-19581	WANDELL 32-7	SI
265032	WELL	SI	03/01/2022	OW	123-21138	WANDELL 33-7	SI
265063	WELL	SI	05/01/2021	GW	123-21166	WANDELL 43-7	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type			
Comment:	See Inspection Doc #699304406 for related shared facilities and equipment		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate x 3		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	See Inspection Doc #699304406 for related shared facilities and equipment		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	chainlink topped with barb wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type:	#		
Comment:	See Inspection Doc #699304406 for related shared facilities and equipment		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	automation		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	plumbed to surface, exposed at surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	See Inspection Doc #699304406 for related shared facilities and equipment					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 251777 Type: WELL API Number: 123-19581 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI, LOTO Form 06A Doc # 403213985.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/30/2022 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: submit test results to the ECMC.

Corrective Action: _____ Date: _____

Facility ID: 265032 Type: WELL API Number: 123-21138 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI, LOTO Form 06A Doc # 403213985.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/12/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 68 Fluid Type: GAS

End Surf Csg Pressure: 2

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 265063 Type: WELL API Number: 123-21166 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI, LOTO Form 06A Doc # 403213985.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/01/2022 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Submit test results to the ECMC.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 8-22-2023 at approximately 1110 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: Civitas/Crestone Peak Resources</p> <p>Location name: Wandell 62N67W 7SWNE</p> <p>Location ID # 336456</p> <p>County: Weld</p> <p>Weather: Sunny, cloudy and clear.</p> <p>Location: Dry.</p> <p>While there, I observed a Multi-well, SI at the time of the inspection.</p> <p>During this inspection, I observed no compliance issues:</p> <p>See attached photos.</p> <p>No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	08/22/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402253	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6228895