

Scout Energy Management LLC
U P 12-27
Loc ID: 314607



Entrance sign if replaced will require additional information.

Well sign missing required information

Scout Energy Management LLC
U P 12-27
Loc ID: 314607



Debris



Stained soils

Scout Energy Management LLC
U P 12-27
Loc ID: 314607



Debris. Stained soil.



Debris

Scout Energy Management LLC
U P 12-27
Loc ID: 314607



Debris on pumping unit



Access road to location

Scout Energy Management LLC
U P 12-27
Loc ID: 314607



Location from Northwest corner



Location from Northeast corner

Scout Energy Management LLC
U P 12-27
Loc ID: 314607



Location from Southwest corner



Location from Southeast corner