


**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad**  
**Location ID: 334129**



**Location Overview: Location is within Black Bear Habitat & in close proximity to High Priority/Density Habitat areas.**

**Section/Township/Range: 1 8S96W**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad**  
**Location ID: 334129**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad**  
**Location ID: 334129**



**Photo # 6737 Improperly stored chemicals/chemical containers**



**Photo # 6753 Check dam & culvert inlet/BMP's need maintenance (near entrance to location) Slope showing signs of lack of stabilization**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad**  
**Location ID: 334129**



**Photo # 6754 Check dam & culvert inlet/BMP's need maintenance (near entrance to location) Slope showing signs of lack of stabilization**



**Photo # 6755 Culvert outlet needs maintenance (near entrance to location)**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad**  
**Location ID: 334129**



**Photo # 6755 Culvert outlet needs maintenance (near entrance to location)**



**Photo # 6761 Check dams need maintenance**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad**  
**Location ID: 334129**



Aug 21, 2023 at 10:33:53 AM  
CO



Aug 21, 2023 at 10:34:16 AM  
CO

**Photo # 6768 Failure to maintain chemical BMP/chemical containment approximately 3/8<sup>th</sup> full of fluid (approximately 5/10<sup>th</sup> of a mile down lease road & 50-75 yards past spur road turnoff to CASS-GARBER pad)**

**Photo # 6771 Failure to maintain chemical BMP/chemical containment approximately 3/8<sup>th</sup> full of fluid (approximately 5/10<sup>th</sup> of a mile down lease road & 50-75 yards past spur road turnoff to CASS-GARBER pad)**