

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad

Location ID: 334129



Photo # 6715 From entrance to location



Photo # 6717 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad
Location ID: 334129



Photo # 6719 Location



Photo # 6722 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad

Location ID: 334129



Photo # 6723 Location



Photo # 6724 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad

Location ID: 334129



Photo # 6726 Debris



Photo # 6730 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad

Location ID: 334129



Photo # 6741 Open ended load line



Photo # 6744 Open ended load line

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad

Location ID: 334129



Photo # 6768 Open cellar/wildlife hazard (approximately 5/10th of a mile down lease road & 50-75 yards past spur road turnoff to CASS-GARBER pad)



Photo # 6769 Open cellar/wildlife hazard Open cellar/wildlife hazard (approximately 5/10th of a mile down lease road & 50-75 yards past spur road turnoff to CASS-GARBER pad)

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad

Location ID: 334129



Photo # 6790 Unused equipment (approximately 2/10th of mile from start of lease road at pig station)



Photo # 6791 Unused equipment (approximately 2/10th of mile from start of lease road at pig station)

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER Pad

Location ID: 334129



Photo # 6792 Unused equipment (approximately 2/10th of mile from start of lease road at pig station)