

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2023

Submitted Date:

08/16/2023

Document Number:

695108556

FIELD INSPECTION FORMLoc ID 308141 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262871	WELL	PR	07/01/2022	CBM	071-07579	LORENCITO 15-9-34-66	PR
264507	PIT	AC	08/22/2002		-	LORENCITO 15-9 ONSITE	AC

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

1

Comment:

IS ACCESSABLE

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 262871	Type: WELL	API Number: 071-07579	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
BradenHead				
Date of Last Brhd Test: 10/14/2015	Annual Brhd Completed?			
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:		
	End Surf Csg Pressure: 0			
Comment:				
Corrective Action:				Date:
Facility ID: 264507	Type: PIT	API Number: -	Status: AC	Insp. Status: AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 264507Lat: 37.091960Long: -104.783969Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: NOComment:

PHOTO 4: PRODUCED WATER PIT/ FLUID LEVEL IS ABOVE FREEBOARD (CONTACTED ZEKE SANCHES WITH EVERGREEN).

Corrective

Lower fluid level so at least two feet of freeboard exists per Rule 909.c.

Date: 08/16/2023**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403498271	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6220234
695108557	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6220229