

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2023

Submitted Date:

08/16/2023

Document Number:

698600921

FIELD INSPECTION FORMLoc ID 336974 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chambers, Kit		Kchambers@ravenwoodlabs.com	
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281152	WELL	PR	03/04/2007	GW	125-09642	BLED SOE 3-26-5-45	PR

General Comment:

Follow up Inspection conducted due to initial findings on Routine Inspection completed 08/02/2023 document number 698600868 and Follow-up Inspection completed 08/07/2023 document number 698600895.

The initial Routine Inspection was conducted in response to Landowner reporting damage to irrigation system pivot arm coming into contact with tubing sticking out of the wellbore. Tubing was forced over by Pivot Arm and split approximately 6" above well cap. Split in tubing is allowing well to continuously vent gas.

Operator stated on August the 9th they had a crew that would be out to secure the well on August 10th with a planned work start time of noon. I notified the Operator at 3:35 PM that repairs have not been completed and well is continuing to vent at the split in the tubing.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	<p>Tubing with valve in wellbore appears to of been pushed by gas pressure high enough it came into contact with irrigation system pivot arm and is bent over. Tubing has split at bend and is venting uncontrolled.</p> <p>Follow up Inspection 8/7/2023 - Well is continuing to vent to atmosphere.</p> <p>Follow up Inspection 8/10/2023 - Well is continuing to vent to atmosphere.</p>		
Corrective Action:	<p>Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).</p> <p>Follow up Inspection 8/10/2023 - Corrective Action Date remains the same to document noncompliance.</p>		Date: <u>08/03/2023</u>

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 281152 Type: WELL API Number: 125-09642 Status: PR Insp. Status: PR**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403499674	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222394
698600939	Well Sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222392
698600940	08/10/2023 Tubing Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222393