

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/14/2023

Submitted Date:

08/16/2023

Document Number:

708300782

FIELD INSPECTION FORM

 Loc ID 324469 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 77330
 Name of Operator: SG INTERESTS I LTD
 Address: 100 WAUGH DR SUITE 400
 City: HOUSTON State: TX Zip: 77007
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Interests, SG		inspection@sginterests.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271432	WELL	PR	02/01/2011	GW	051-06057	FEDERAL 11-90-24 1	PR

General Comment:[COGCC Inspection Report Summary](#)

On 8/14/2023 at approximately 14:15, Compliance Inspector Matthew Morris conducted an on-site inspection at SG INTERESTS I LTD, FEDERAL 11-90-24-611S90W/24NWSE at Location ID #324469 in Gunnison County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Storage of unused supplies/equipment
- 2) Bradenhead valve not accessible
- 3) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Fan shroud stored near pump jack.		
Corrective Action:	Remove unused supplies equipment to comply with Rule 606.	Date:	08/31/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Livestock paneling		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire fencing		
Corrective Action:		Date:	

Equipment:		corrective date
Type: Bird Protectors	# 5	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	#	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 2	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Bradenhead valve is not accessible.	
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date: 08/26/2023
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
	Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 271432 Type: WELL API Number: 051-06057 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Rip Rap				
Gravel						
Ditches						
		Retention Ponds				
		Ditches				
Berms						
		Drains				
Check Dams						
		Gravel				
Retention Ponds						
		Check Dams				
Seeding						
		Berms				
		Compaction				
		Other	Fail			Insufficient erosion control
		Culverts				
Rip Rap						
Sediment Traps						
		Sediment Traps				
Culverts						

Comment: 1) Insufficient erosion control of lease road; road is washing out
2) Rill erosion cutting through lease road

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 08/31/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403499695	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222426
708300794	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222420