

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2023

Submitted Date:

08/17/2023

Document Number:

698600923

**FIELD INSPECTION FORM**Loc ID 337040 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

11 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	
, Engineering		dnr_cogccengineering@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
Chambers, Kit		Kchambers@ravenwoodlabs.com	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281797	WELL	PR	10/01/2021	GW	125-09728	BENNETT-STATE 9-16-5-45	PR

**General Comment:**

Routine Inspection.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained county road. Two track has not been maintained.		
Corrective Action	Repair and maintain lease road to comply with rule 603.I.	Date:	09/18/2023
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Well sign at remote Gas Meter Run location.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign at well location is out of bracked an on the ground..		
Corrective Action:	Repair, replace, install sign to comply with Rule 605.a.	Date:	09/18/2023
Emergency Contact Number:			
Comment:	Emergency contact #877-425-4882 posted on well sign at remote Gas Meter Run is invalid and appears to be disconnected or no longer in service.		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	09/18/2023
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Well location has vegetation growing inside fencing.		
Corrective Action:	Comply with Rule 606.	Date:	08/25/2023
Type	WEEDS		
Comment:	Remote Gas Meter location has vegetation growing inside fencing.		
Corrective Action:	Comply with Rule 606.	Date:	08/25/2023
Type	DEBRIS		
Comment:	Production related debris left inside and outside wellhead fencing.		
Corrective Action:	Comply with Rule 606.	Date:	08/25/2023
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Stock Panel Fencing around equipment at remote Gas Meter location.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock Panel Fencing around surface equipment at well location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Supply gas Liquids Knock Out Vessel.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located off CR BB. Gas Meter Run. Undated Chart in Meter Box. Meter Calibration/Test Log dated 7-15-20. Well Inlet Valve appears to be open, bad valve. Gas Outlet Valve appears to be closed, bad valve. Water Outlet valve closed.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	09/18/2023
Type: Pump Jack	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Cement Pad. Pump Jack has been removed but cement pad is still inside fencing.		
Corrective Action:	Comply with Rule 606.	Date:	09/18/2023
Type: Other	# 1		
Comment:	Remote metal Meter Shed.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods removed and tubing in wellbore. Tubing joint is sticking out of well cap approximately 12'. Tubing valve closed and not connected. Casing valve closed. Bad valves at Gas Meter Run.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).	Date:	09/02/2023
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	08/28/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 281797 Type: WELL API Number: 125-09728 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment:

Pump Jack removed. Rods have been removed tubing in the wellbore. Tubing valve is closed and not connected and stick up out of well approximately 12'. Casing valve closed. Gas Meter Run Valves: Well inlet valve appears to be open, bad valve. Gas outlet valve appears to be closed, bad valve. Water outlet valve closed.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as SI. Based on current valve settings at the wellhead and Meter Run the well appears to be SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 09/18/2023

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403500459	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223149">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223149</a>
698600947	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223144">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223144</a>