

Provide 24 hour notice of MIRU to Bob VanSickle at 719-336-2843. If well is a producer, run CBL to verify cement coverage. If well is a dry hole set plugs at the following depths: 1) 40 sks cement +/-50' above any significant Red Cave zone and/or any other significant hydrocarbon bearing zone. 2) 40 sks cement 1/2 in and 1/2 out of 8 5/8" surface casing. 3) 10 sks cement top 8 5/8" csg, cut 4 ft below GL, weld on plate 4) 5 sks cement in rat hole and mouse hole.