

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2023

Submitted Date:

08/18/2023

Document Number:

712700539

**FIELD INSPECTION FORM**Loc ID 333963 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		Maralextech@gmail.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276035	WELL	PR	10/27/2005	CBM	067-09016	KEEGAN PATRICK 33-7-11 2A	PR
298720	WELL	PR	02/09/2009	CBM	067-09631	KEEGAN PATRICK 33-7-11 3C	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700209 submitted on 5/23/2023.

Equipment inventory included in previous FIR, location equipment unchanged.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Present		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Observed CO-State Class B listed weed species (Musk thistle, and Russian Knapweed) across northeast corner of location, around wellhead/pumpjacks, and around separators. See Photos Corrective action was identified in FIR Doc.#712700209. Corrective action date is retained.		
Corrective Action:	Control weeds per Rule 606.		Date: 06/06/2023
Type	UNUSED EQUIPMENT		
Comment:	Corrective action identified in FIR Doc.#712700209 has been completed.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Observed lube oil leak from the stuffing box at both wellheads. Impacted material on ground. Corrective action was documented in FIR Doc.#712700209. Corrective action date is retained.		
Corrective Action:	Comply with Rule 1002.f.(2).d. Increase maintenance on equipment, cleanup stained material and review self inspection processes.		Date: 06/07/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Sound abatement walls.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:	One separator vent stack missing bird protection screen. This comment was identified in FIR Doc.#712700209.		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 276035 Type: WELL API Number: 067-09016 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/25/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 298720 Type: WELL API Number: 067-09631 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/25/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONEEnd Surf Csg Pressure: 1Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Ditches	Pass			

Comment: No visible erosion or sediment migration observed during inspection.Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403502445	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6225073">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6225073</a>
712700546	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6225058">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6225058</a>