

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2023

Submitted Date:

08/21/2023

Document Number:

698600937

FIELD INSPECTION FORM

Loc ID 303113 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 38 PALMER CREST CT
City: SPRING State: TX Zip: 77381

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 22 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|------------------------------|---------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 252480 | WELL | PR | 07/04/1980 | GW | 125-06355 | ECKLEY-KITZMILLER 1-5 | PR |

General Comment:

[Routine Inspection.](#)

| Location | | | |
|--|--|--------|------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track off maintained County Road. | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Well sign located on well fencing | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Contents/Quantity/Hazard Placard on Produced Water Open Top is unreadable. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 10/21/2023 |
| Type | OTHER | | |
| Comment: | Well sign located at two track and main access road intersection. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Well sign posted on Meter Shed door. | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | No Emergency contact information posted at Produced Water Open Top Pit. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 09/21/2023 |
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Pump Jack belt drive guard noted on ground inside fencing. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Stained soils around wellhead and pumping unit. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. | Date: | 09/21/2023 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | <input style="width: 100%;" type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Stock Panel Fencing around Open Top Pit location. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Type | OTHER | | |
| Comment: | Stock Panel Fencing around Gas Meter Run location. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Stock Panel Fencing around surface equipment at well location. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric Motor. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Pump Jack Power and Control Panel. | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Metal Meter Shed. | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # | | |
| Comment: | Gas Meter Run. Chart in Meter Box dated 8-1-23. Meter Calibration/Test Log dated 3-27-23. Well Inlet Valve open. Gas Outlet Valve open. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. Rods and tubing in wellbore. Tubing valve open. Casing valve open. | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Pump Jack Cement Pad. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead Plumbed to surface. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------|---------|-----------------------|
| PRODUCED WATER | 1 | OTHER | Open Top | | 40.255000,-102.419610 |
| Comment: | Fiberglass Open Top pit with Wildlife screening (wire netting). Pit Contents/Quanity/Hazard Placard is unreadable. No emergency contact information posted. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|-----------|--|
| Condition | |
|-----------|--|

| | |
|---------------------------|--|
| Other (Content) | |
| Other (Capacity) 210 BBLS | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| Yes/No | NO | | |
|--------------------|----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 252480 Type: WELL API Number: 125-06355 Status: PR Insp. Status: PR

Producing Well

Comment: Rods and tubing in wellbore. Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.

Electronic Well File reflects last Production/Status reported 6/1/2023 and Well Status as PR. Based on current valve settings the well is PR.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403503181 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6226094 |
| 698600962 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6226085 |