



Home (<https://www.weld.gov/Home>) / Government (<https://www.weld.gov/Government>) / Departments (<https://www.weld.gov/Government/Departments>) / Office of Emergency Management (<https://www.weld.gov/Government/Departments/Office-of-Emergency-Management>) / LEPC and Oil & Gas Information (<https://www.weld.gov/Government/Departments/Office-of-Emergency-Management/LEPC-Information-Spill-Report-Form>) / Weld OEM Spill Report Form

Weld OEM Spill Report Form

Submission complete

Thank you for submitting a spill report form.

Company

Company name	DPC Midstream
Address	6900 E Layton Ave, Suite 900
City	Denver
State	Colorado
Zip code	80237

Contact Information

Contact person	Chandler Cole
Contact phone	970-378-6373
Contact email	chandler.e.cole@p66.com

About the Spill

Date incident occurred	08/15/2023
How long did the spill/ release occur	unknown
Was 9-1-1 called for this incident	No
Longitude	-104.993402
Latitude	40.310182
Fire depatment/district	Berthoud Fire
Where did the incident occur?	Oil and gas facility/pipeline

Oil and Gas Incident

Well site name	Markham (BZ7-1-2-19-7-1) 8/2023
Section	15
Township	4N
Range	68W
Where did the spill occur	Pipeline
Other place the spill occurred	
Have you submitted a form 19	Yes
Form 19 report number	403498466

Chemical Facility / Other

Is the facility name and address the same as company name and address?

Facility name

Facility address

City

Zip code

On a Roadway

Nearest intersection

Mile post number

Is there an accident report or run report associated with this spill?

Report number

In a Waterway

Name of waterway, irrigation ditch, or a retention pond

Nearest intersection or address

Mile post number

Product Spilled

Product spilled condensate

Number of barrels spilled 1

Number of gallons spilled

Emergency precautions taken N/A

Extremely hazardous substance No

Acute or chronic health risks No

Please explain acute or chronic health risks

Did the spill affect or end near a waterway, irrigation ditch, or a retention pond? No

Name of the waterway, irrigation ditch, or a retention pond

What caused the spill/release? Equipment failure

What caused the spill or release?

What caused the spill?

Narrative

Include specific incident information and mitigation actions taken to stop and clean-up the spill/release

On 8/9/2023, DCP Midstream was notified of a potential environmental concern on an above-ground valve on a pig launcher next to the meter shed. The pig launcher's valve/piping and meter shed were permanently removed from the location on 8/15/23. The pipeline was pigged before the removal activities. After the launcher and piping were removed, a cap was welded to the open end of the pipeline. On 8/15/23, DCP's contract roustabout crew alongside a third party environmental consultant began excavation of impacted material around the gas gathering line riser. Approximately 12 cubic yards of impacted material were removed and hauled to Buffalo Ridge Landfill. Confirmation soil samples were collected from the 4 sidewalls and floor of the excavation underneath the riser and submitted to Summit Scientific laboratory in Golden, CO for analysis of CECMC Table 915-1 TPH and Organic Compounds of Concern. Laboratory results are pending and will be provided with the Supplemental Form 19.

Upload documentation collected

Figure 1 - Topo.pdf

Acknowledgement

I acknowledge that a written follow-up notice must be submitted to Weld County OEM/LEPC as soon as practicable after the release. The follow-up notice must update information included in the initial notice and provide information on actual response actions taken and advice regarding medical attention necessary for citizens exposed.