

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 08/22/2023 Document Number: 403253060

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10459 Contact Person: James Miller Company Name: EXTRACTION OIL & GAS INC Phone: (720) 974-7460 Address: 370 17TH STREET SUITE 5200 Email: jmiller@civiresources.com City: DENVER State: CO Zip: 80202 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 459452 Location Type: Production Facilities Name: Kallsen 24-9 #1, Madison 23-9 Number: County: ADAMS Qtr Qtr: SESW Section: 9 Township: 1S Range: 65W Meridian: 6 Latitude: 39.972581 Longitude: -104.669600

Description of Corrosion Protection

Extraction's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, Extraction will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. Extraction retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

Extraction's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, Extraction ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 460287 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 320034 Location Type: Well Site
Name: KALLSEN 24-9-61S65W Number: 9SESW
County: ADAMS No Location ID
Qtr Qtr: SESW Section: 9 Township: 1S Range: 65W Meridian: 6
Latitude: 39.975070 Longitude: -104.672560

Equipment at Start Point Riser: Separator

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 01/23/1981
Maximum Anticipated Operating Pressure (PSI): 70 Testing PSI: 70
Test Date: 04/10/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 460286 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 320522 Location Type: Well Site
Name: MADISON-61S65W Number: 9NESW
County: ADAMS No Location ID
Qtr Qtr: NESW Section: 9 Township: 1S Range: 65W Meridian: 6
Latitude: 39.978240 Longitude: -104.672010

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 02/10/2005
Maximum Anticipated Operating Pressure (PSI): 500 Testing PSI: 230
Test Date: 04/10/2018

OFF LOCATION FLOWLINE Abandonment Verification

Date: 10/21/2022

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

Description of Abandonment Verification:

The flowline (00109530FL) serving the Madison 23-9 (05-001-09530) was removed in its entirety via the open trench method. The trench was backfilled and the land surface was graded.

OPERATOR COMMENTS AND SUBMITTAL

Comments Form 44 filed to report POST-ABANDONMENT notification. The following flowlines were removed in their entirety: 00109530FL: serviced the Madison 23-9 (05-001-09530)
All other related flowlines will remain as previously reported.
Updated GIS data attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 08/22/2023 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  **Director of COGCC** Date: 8/29/2023

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

403253060	Form44 Submitted
403498485	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

Financial Assurance	Missing GIS data for the 00107732FL flowline.	03/03/2023
---------------------	---	------------

Total: 1 comment(s)