

Inspection Photos

API: 061-06394

Operator: STRACHAN EXPLORATION INC

Inspection Date: 8/24/2023



Inspection Photos



Photo 1. Facing toward the offsite tank battery location. This tank at red arrow is not in use and needs to be removed.



Inspection Photos



Photo 2. fence around the tank is inadequate to prevent livestock entry and is not maintained. The berm around the tank is insufficient to contain a spill (150% of tank capacity) and has animal borrows the sides.



Inspection Photos



Photo 3. There is stained soils that need to be cleaned up



Inspection Photos



Photo 4. There is unused disconnected pipe that needs to be removed.



Inspection Photos

Aug 24, 2023 at 10:33:17 AM



Photo 5. Facing northwest toward the wellsite.



Inspection Photos



Photo 6. There is oily fluid in the containment next to the pump jack. Oily fluid has spilled onto the ground and needs to be cleaned up.

