

# Inspection Photos

API: 061-06403

Operator: STRACHAN EXPLORATION INC

Inspection Date: 8/24/2023



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing toward the offsite tank battery location.





## Inspection Photos



**Photo 2.** The sign is faded and does not meet the signage requirements of Rule 605.e.





## Inspection Photos



**Photo 3.** The fence around the tank battery is inadequate to prevent livestock entry and is not maintained.



## Inspection Photos



**Photo 4.** Facing southwest toward the wellsite..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API: 061-06403 | Date: 8/24/2023



## Inspection Photos



**Photo 5.** Facing toward the tank. The berm around the tank is inadequate to contain a spill.



## Inspection Photos



**Photo 6.** The well sign is faded and does not meet the signage requirements.

