

Inspection Photos

API: 061-06368

Operator: STRACHAN EXPLORATION INC

Inspection Date: 8/24/2023



Inspection Photos



Photo 1. Facing toward the offsite meter run and open top condensate tank located about 2000' east of the wellsite.



Inspection Photos



Photo 2. The berm around the tank has been built up however soils were not compacted to be impermeable.



Inspection Photos



Photo 3. The netting on the open top tank is torn and needs repair. Previous corrective action was not completed.



Inspection Photos



Photo 4. The fence around the open top tank is inadequate to prevent livestock entry and is not maintained. Previous corrective action was not completed.



Inspection Photos

Aug 24, 2023 at 10:45:12 AM



Photo 5. The offsite tank battery sign is faded and does not meet the signage requirement of rule 605.



Inspection Photos

Aug 24, 2023 at 10:49:24 AM



Photo 6. Facing toward the wellsite. The labeling on the tank is faded and peeled off. The berm around the tank has been built up however soils were not compacted to be impermeable.



Inspection Photos



Photo 7. Drone photo looking down at the open top tanks shows no netting over the tank. Tank is approximately $\frac{3}{4}$ full of crude oil. Previous corrective action was not completed.

