

Inspection Photos

API: 061-06365

Operator: STRACHAN EXPLORATION INC

Inspection Date: 8/24/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing east toward the location.



Inspection Photos



Photo 2. Drone aerial photo facing west at the north side of the location



Inspection Photos



Photo 3. Facing southeast at the location. The two large volume tanks do not have proper labeling or secondary containment. If the tanks are unused then they need to be removed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06365 | Date: 8/24/2023

Inspection Photos



Photo 4. The south toward the wellsite and production equipment. The fence around the equipment is inadequate to prevent livestock entry. Cattle track have been observed inside the 2 strand fence.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06365 | Date: 8/24/2023

Inspection Photos



Photo 5. Facing southeast toward the tanks. Fencing is inadequate around the tanks.



Inspection Photos



Photo 6. The netting on the open top tank needs to be repaired to prevent wildlife entry.



Inspection Photos



Photo 7. Facing toward the pumpjack.



Inspection Photos



Photo 8. Facing at the north side of the location. The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. Berm is insufficient to contain a spill (150% of tank capacity). Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06365 | Date: 8/24/2023