

# Inspection Photos

API: 061-06296

Operator: STRACHAN EXPLORATION INC

Inspection Date: 8/24/2023



## Inspection Photos



**Photo 1.** Facing toward the wellsite.



## Inspection Photos



**Photo 2.** It appears oily soils were cleaned up around the barrel containment.



## Inspection Photos



**Photo 3.** Facing northeast toward the tank battery.



## Inspection Photos



**Photo 4.** The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. Previous corrective action was not completed.



## Inspection Photos



**Photo 5.** The berm is inadequate to contain a spill as it is piled up against the tank and would spill over the berm along this side. Previous corrective action was not completed.

