

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

08/31/2023

Document Number:

713600138

FIELD INSPECTION FORM

 Loc ID 324837 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 383 INVERNESS PKWY, STE 360City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments4 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HARMS JASON		jason@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213033	WELL	PR	03/01/2023	OW	061-06394	STAVELY 1-26	RI

General Comment:

On 8/24/2023, Ryan Costa conducted a location inspection.
 See attached photos and additional details within this report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	There is unused pipe, cable, and a tank that need to be removed. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606.	Date:	06/29/2023
Type	OTHER		
Comment:	There is oily fluid that has overtopped the containment and spilled out by the pumpjack. Corrective action will remain out of compliance until completed.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Immediate clean up. Implement or modify BMPs for improved material handling and spill prevention.	Date:	06/29/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	06/29/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3				
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	The berm around the tank is insufficient to contain a spill (150% of tank capacity) and has animal borroughs on the sides. Berms need to be compacted and built to be impermeable. Corrective action will remain out of compliance until completed.			

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.	Date:	06/29/2023
--------------------	--	-------	------------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600139	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238206