

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/24/2023

Submitted Date:

08/31/2023

Document Number:

713600142

FIELD INSPECTION FORM

Loc ID 324832 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 6 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
HARMS JASON		jason@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213007	WELL	PR	08/14/1987	GW	061-06368	LAS ANIMAS 1-1	RI

General Comment:

On 8/24/2023, Ryan Costa conducted a follow up location inspection. See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	The labeling on the tanks are faded and peeled off. Corrective action will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/29/2023

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	The fence aournd the tanks is missing or inadequate to prevent livestock entry. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	06/29/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1		Open Top		38.439000,-103.062280
Comment:	The netting on the tank is torn and needs to be repaired. Operator was notified the day of initial inspection for immediate repair. Previous corrective action was not completed.				
Corrective Action:	Install or repair wildlife protection equipment.				Date: 06/29/2023

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient		
Comment:	The berm around the tank has been built up however soils were not compacted to be impermeable.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 06/29/2023

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		Open Top		38.438720,-103.069100
Comment:	There is no netting to prevent wildlife entry of the open top tank at the wellsite. Operator was notified the day of intial inspection for immediate install. Previous corrective action was not completed.				

Corrective Action: Install or repair wildlife protection equipment.	Date: <u>07/01/2023</u>
--	-------------------------

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600143	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238209