



Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

Photo #1 sign at Wellhead. There is an old pulling unit at the wellhead. The rig is laid down on the truck. There is other workover debris and trash at the well. There is a Warning Letter, doc 2193064 in the well file for a lack of MIT on this TA well. To date (8/24/2023) there is no record of this well being MIT'd.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

Photo #2 Old rig at well, multiple tanks, trash and debris.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

Photo #3 3 temporary tanks near well and trash. The well itself has a three wire fence.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

Photo #4 Old International Rig on location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

Photo #5 debris from Work over.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

Photo #6 close up of wellhead and workover debris.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #7 waxy buildup.**





Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #8 trash and debris.**





**Photo #9 Trailer tank on location.**

Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #10 Production tank near Irrigation Ditch.**





Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

Photo #11 Sign at Production Tank.





Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #12** Appears that this is the Poly flowline that is coming from the 12-1 well. There is no Sign identifying this tank as related to the 12-1 well.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #13 Poly line is buried in the tank Berm.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo #14 Poly line entering the Production Tank.**

Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
well 0057-06374  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #15 Tank is fenced.**