

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2023

Submitted Date:

09/01/2023

Document Number:

694500596

FIELD INSPECTION FORMLoc ID 313419 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 77900

Name of Operator: SHAWNEE OIL DEVELOPMENT CO INC

Address: P O BOX 300

City: KEVIN State: MT Zip: 59454

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
hawkins, James	(406) 873-5277	jhawkins@bresnan.net	owner operator
Nygaard, Kerma		nygaard745@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223623	WELL	PR	05/01/2023	OW	081-60020	USA SHAW 19	TA

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			
Crude Oil	Flow Line	<= 1 bbl			
Comment:	The spill was NOT at a Flow Line, but something needed to be slected. spill is 20 west of wellhead, seeping out of the ground, see attached photos.				
Corrective Action:	. A Form 19 Spill report should be submitted			Date:	09/22/2023
Crude Oil	WELLHEAD	<= 1 bbl			
Comment:	estamated to be more than a bbl our of containment.				
Corrective Action:	. A Form 19 Spill report should be submitted			Date:	09/22/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:	appeared to be a white PVC blind plug in a valve on the tank, the blind plug was leaking fluid.					
Corrective Action:	Use appropriate piping and plugs.			Date:	09/22/2023	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Inadequate
Comment:	maintenance was selected as Inadequate as it is not clear if the tank battery would hold fluid. The integrity of the containment should be evaluated and repaired if necessary.			
Corrective Action:	The integrity of the containment should be evaluated and repaired if necessary.			Date: 09/29/2023

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	223623	Type:	WELL	API Number:	081-60020	Status:	PR	Insp. Status:	TA

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500598	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240472