

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad

Location #: 335358



Photo # 7838 From entrance to location



Photo # 7839 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad
Location #: 335358



Photo # 7840 Location



Photo # 7841 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad

Location #: 335358



Photo # 7842 Location



Photo # 7843 Flowline heating insulation open ended

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad

Location #: 335358



Photo # 7844 Hole in liner/liner needs maintenance



Photo # 7846 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad

Location #: 335358



Photo # 7848 Hole in liner/liner needs maintenance



Photo # 7849 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad

Location #: 335358



Photo # 7851 Hole in liner/liner needs maintenance



Photo # 7852 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad

Location #: 335358



Photo # 7853 Hole in liner/liner needs maintenance



Photo # 7854 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad
Location #: 335358



Photo # 7853 Holes in liner/liner needs maintenance




Photo # 7855 Holes in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad
Location #: 335358



Photo # 7861 Debris




Photo # 7862 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY O30NE Pad
Location #: 335358



Photo # 7858 Tank labels peeling off