

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 7789 From entrance to location



Photo # 7791 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 7792 Location



Photo # 7793 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 7794 Location



Photo # 7795 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 7796 Location

Photo # 7797 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 1501 From inspection 708900837 conducted on 06/23/2023 Hole in production tank/tank corrosion

Photo # 7833 Hole in production tank/tank corrosion

Inspection Photos

Location Name: CAERUS PICEANCE LLC B31 Pad

Location #: 335307



Photo # 1503 From inspection 708900837 conducted on 06/23/2023 Hole in production tank/tank corrosion



Photo # 7825 Hole in production tank/tank corrosion

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 1505 From inspection 708900837 conducted on 06/23/2023 Hole in production tank/tank corrosion

Photo # 7804 Hole in production tank/tank corrosion

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location #: 335307



Photo # 7826 Hole in production tank/tank corrosion



Photo # 7827 Hole in production tank/tank corrosion