

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2023

Submitted Date:

09/03/2023

Document Number:

708901525

FIELD INSPECTION FORM

Loc ID 335307 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
28 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260285	WELL	PR	11/08/2013	GW	045-07841	COUEY 31-8 (B31)	PR
260286	WELL	PR	07/29/2002	GW	045-07842	COUEY 31-7 (B31)	PR
260287	WELL	PR	12/06/2002	GW	045-07843	COUEY 31-2 (B-31)	PR
260288	WELL	PR	08/06/2002	GW	045-07844	SHAEFFER 31-3 (B31)	PR
262207	WELL	PR	05/10/2012	GW	045-08003	COUEY 31-7B2 (B31)	PR
262208	WELL	PR	07/23/2002	GW	045-08004	COUEY 31-1C2 (B-31)	PR
262968	WELL	PR	08/09/2002	GW	045-08077	COUEY 30-15 (B31)	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 08/31/2023 at approximately 10:12 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at CAERUS PICEANCE LLC B31 Pad Location # 335307 in Garfield County Colorado.
 Please refer to inspection 708900837 conducted on 06/23/2023, 2 of the 3 previous corrective actions have been completed. Corrective action for Production tank needs inspection & maintenance has not been completed & CA date remains 07/24/2023. Location is within High Priority/Density/Black Bear Habitat areas. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Tanks & Berms - Production tank needs inspection & maintenance with a CA date of 07/24/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Location

Lease Road:			
	Type	Access	
	comment:		
	Corrective Action		Date:

Overall Good:

Signs/Marker:			
	Type	OTHER	
	Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.	
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:
	Type	TANK LABELS/PLACARDS	
	Comment:		
	Corrective Action:		Date:
	Type	BATTERY	
	Comment:		
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	911/970-285-2615	
	Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	Cattle panels	
	Corrective Action:		Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
	Comment:	Summit Midstream	
	Corrective Action:		Date:
Type: Gas Meter Run	# 7		
	Comment:		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Nitrogen tank		
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Pressure transducers located on all bradenhead, all bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	In separate containment with single 300 bbl condensate tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Unlined containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Tank appears to be compromised, hole & corrosion near top of tank. In separate containment with 1000 gal methanol tank as you come onto location. Appears there's a coated replacement tank sitting on location but the compromised tank has not been taken out of service & replaced yet.				

Corrective Action:	All in service tanks & process vessels will be inspected & maintained.	Date:	07/24/2023
--------------------	--	-------	------------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Unlined containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment: Centralized containment with 2 of the 300 bbl condensate tanks					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Unlined containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment: Centralized containment					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Unlined containment				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	260285	Type:	WELL	API Number:	045-07841	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	260286	Type:	WELL	API Number:	045-07842	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	260287	Type:	WELL	API Number:	045-07843	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	260288	Type:	WELL	API Number:	045-07844	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	262207	Type:	WELL	API Number:	045-08003	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	262208	Type:	WELL	API Number:	045-08004	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	262968	Type:	WELL	API Number:	045-08077	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						Areas of light compaction
		Ditches				
Gravel						Sparse
		Culverts				
Ditches						
		Gravel				Sparse

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Small amount of erosion on slope behind tank battery at S/SW end of location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Tanks & Berms for observed compliance issue.	smelserw	09/03/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901526	Inspection 708901525 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240663
708901527	Inspection 708901525 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240664