

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2023

Submitted Date:

08/28/2023

Document Number:

712700586

FIELD INSPECTION FORMLoc ID 311995 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|--------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , General | | sjninspections@ikavenergy.com | All SW Inspections |
| Pesicka, Conor | | conor.pesicka@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 215272 | WELL | PR | 09/01/2019 | CBM | 067-06877 | FRANCIS WHITE A 1 | PR |
| 293294 | WELL | PR | 11/05/2007 | CBM | 067-09419 | FRANCIS WHITE A 3 | PR |

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location

| | | | |
|--------------------|------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Locked gate, 2C40 key. | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign not posted at oil and gas location. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 09/28/2023 |

Emergency Contact Number:

Comment: Wellhead sign not posted. No 24 hour emergency contact number posted.

Corrective Action: Install sign to comply with Rule 605.a.

Date: 10/04/2023

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Cattle panel enclosure around separators, tank, meterhouse, and telemetry. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Cattle panel | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Above ground valve, pipe fence. | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | On three sides, T-post and barbed wire. | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------|------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 2 | | |
| Comment: | PVC access | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------------------|---|------------------|
| Type: Prime Mover | # 2 | |
| Comment: | Natural gas motor | |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 2 | |
| Comment: | Housed together | |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 2 | |
| Comment: | Wellhead | |
| Corrective Action: | | Date: |
| Type: Deadman # & Marked | # 4 | |
| Comment: | One unmarked guy anchor. | |
| Corrective Action: | Mark guy anchor per Rule 1003, or remove if not serviceable or not needed for ongoing operations. | Date: 09/11/2023 |
| Type: Flow Line | # 4 | |
| Comment: | 2-3" lines from wellhead to separator. 2-1" lines from separator to prime mover. | |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # 2 | |
| Comment: | 3" lines from separator to meterhouse. Calibration date 6/1/2023. | |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 3 | |
| Comment: | Telemetry | |
| Corrective Action: | | Date: |
| Type: Pump Jack | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|----------------------|
| PRODUCED WATER | 1 | <100 BBLS | PBV STEEL | | 37.158790,-10.809290 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected FacilitiesFacility ID: 215272 Type: WELL API Number: 067-06877 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/21/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 293294 Type: WELL API Number: 067-09419 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/21/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--------------------------------|
| Gravel | Pass | | | | | |
| Waddles | Pass | Ditches | Pass | | | |
| Ditches | Pass | Culverts | Pass | Material Handling And Spill Prevention | Pass | Containers within containment. |
| Compaction | Pass | Gravel | Pass | | | |

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 712700591 | Well Location Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240927 |