

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324155

Date: 8/22/2023



SW Corner of Location – Photo #06045



Wellhead – Photo #06043

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324155

Date: 8/22/2023



Separators – Photo #06046



Tank Battery – Photo #06047

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324155

Date: 8/22/2023



Rill Erosion Cutting Through Access Road – Photo #06041



Rill Erosion Cutting Through Access Road – Photo #06042

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324155

Date: 8/22/2023



Insufficient Erosion Control – Photo #06048



Insufficient Erosion Control – Photo #06049

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324155

Date: 8/22/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06044



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06051