

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/04/2023

Submitted Date:

09/05/2023

Document Number:

693701074

FIELD INSPECTION FORM

Loc ID: 465923 Inspector Name: ALLISON, RICK On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 76840
Name of Operator: SCHNEIDER ENERGY SERVICES INC
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		jeff@schneiderenergy.com	
		kbothwell@schneiderenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466141	OFF-LOCATION FLOWLINE	AC	07/18/2019		-	Wellhead Line 1	EI
466142	OFF-LOCATION FLOWLINE	AC	07/18/2019		-	Wellhead Line 1	EI
466376	OFF-LOCATION FLOWLINE	AC	07/31/2019		-	Wellhead Line 1	EI
466657	OFF-LOCATION FLOWLINE	AC	08/13/2019		-	Wellhead Line 1	EI

General Comment:

Operator has removed all tank battery/production equipment from location. Gas sales line riser remains on location.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume		corrective date
Type: Gathering Line	# 1			
Comment:	Gathering line/gas sales line riser remains on location			
Corrective Action:				Date:
Type: Flow Line	#			
Comment:	If off-location flowlines (wellhead lines for Weld Co. Drilling Fund #1 and #2, and #3 and #4) have been removed, submit Form 44 Abandonment Verication pursuant to Rule 1105.f.(2)			
Corrective Action:	If off-location flowlines (wellhead lines for Weld Co. Drilling Fund #1 and #2, and #3 and #4) have been removed, submit Form 44 Abandonment Verication pursuant to Rule 1105.f.(2)			Date: <u>11/02/2023</u>

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 466141 Type: OFF- API Number: - Status: AC Insp. Status: EI

Facility ID: 466142 Type: OFF- API Number: - Status: AC Insp. Status: EI

Facility ID: 466376 Type: OFF- API Number: - Status: AC Insp. Status: EI

Facility ID: 466657 Type: OFF- API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: All production equipment has been removed from the location. Operator submitted Form 27 Doc#402948608 (Remediation Project #21910) with a plan to conduct Rule 911.a. required site investigation commencing 2/18/2022. No Supplemental Form 27 has been received to document the site investigation results.

Pursuant to Rule 913.d. an Operator shall adhere to the proposed Implementation Schedule and obtain Director approval for changes to the Implementation Schedule. Pursuant to Rule 913.e. an Operator shall provide quarterly update reports in a Supplemental Form 27. The approved Form 27 provided for a one time report within 90 days of receiving laboratory analytical results.

No Supplemental Form 27 reports have been received.

Corrective Action: Submit Supplemental Form 27 with analytical results of site investigation. Date: 11/02/2023

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693701075	Production Facility Looking East	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6241201